

July 30, 1984

Clifton Precision

Attention: Mr. Paul Bohnsack, Mgr. Safety & Security

2734 Hickory Grove Rd. Davenport, IA 52808

Re: RCRA Hazardous Waste Inspection

Dear Mr. Bohnsack:

Enclosed is a hazardous waste inspection report of your facility. We believe you will find the report self-explanatory and concur with report recommendations.

Please note: weekly inspections of container storage areas must be conducted and documented.

Also, please review and correct other deficiencies noted during this inspection.

This report will be forwarded to our Hazardous Waste Section for additional comment.

Should you have any questions or would like to discuss this report further, feel free to contact our office.

Sincerely,

FIELD SERVICES DIVISION

Merritt W. Van Lier

Regional Administrator

Regional Office #6

MWV:aw

Enc.

xc: Rod Vlieger, Central Office
Donald Sandifer, P.E., EPA, Kansas City, MO
File

RO0337091 RCRA RECORDS CENTER 11 HV - 97

IOWA DEPARTMENT OF WATER, AIR AND WOTE MANAGEMENT Page _1 Of 5

Report Of Investigation

INVESTIGATION DATE Current 7/11/84 Last 7/13/83 TO: (Facility Name, Location & Address) Clifton Precision	Region No. 6 Stamp) P. O. Box 27 Washington, Iowa 52353				
2734 Hickory Grove Rd. Davenport, IA 52808	Paul Bohnsack, Manager of Safety & Security				
RE:(Specify Investigation Purpose Or Cite Rule)					
Hazardous Waste Inspection IAD005268420					

OBSERVATIONS/RECOMMENDATIONS

Clifton Precision, Instruments and Life Support Division, manufactures aircraft instrumentation, breathing oxygen regulators and oxygen generating equipment. This facility also has a bottle cleaning and charging station for small high pressure tanks used by the military in infrared night scopes.

Unit processes used by Clifton Precision are: electroplating, anodizing painting, aluminum conversion, heat treating, general manufacturing and assembly.

The hazardous wastes generated and stored on-site at Clifton Precision are primarily from metal parts degreasing, cleaning, heat treating and electroplating. The wastes generated include: (1) trichloroethylene, EPA no. F001; (2) spent pickling acids, EPA no. F009; (3) spent plating baths, EPA no. F007; (4) plating tanks sludges, EPA no. F008; (5) 1,1,1 trichloroethane, EPA no. F001; (6) sodium nitrite and sodium nitrate, EPA no. F011; (7) non-halogenated solvents including isopropyl alcohol toluene, "Stoddard" solvent, lacquer thinner and methyl alcohol, EPA no. F005; and (8) non-halogenated solvents including acetone, cyclohexane and xylene, EPA no. F003.

This facility currently has interim status to store hazardous waste over 90 days. A Part B application was submitted by this facility for a permit to store hazardous waste over 90 days, approximately one year ago. This facility was inspected for compliance with regulations as they apply to a facility with interim status to store hazardous waste.

NOTE: 40 CFR references are Federal hazardous waste rules as promulgated by EFA from May 19, 1980 through June 30, 1983 (Parts 260 - 265) and as adopted by the State of Iowa (900--I.A.C. 45) on September 20, 1983.

SUSPENSE DATE	Signature Date					
	Inspector	1.11:1:				
	David N. Whiting lawy	11. Walting	7/17/84			
/	Regional Administrator	+1: 3/ (1.1	111			
	Merritt W. Van Lier Minus	(11) Can Lui	2/3/184			
Enclosures (Specify)						
Distribution: Regional Office: Central Office: Inspected Facility						

Company Name <u>CLIFTON PRE</u>	CISION Date of Inspectlo	on 7/11/8/	F	ge 2 of 5
		7/11/04	IAD O	0 5 2 6 8 4
	HAZARDOUS WASTE MANAGEMENT FA	CILITY		
	General Administrative Requir	ements		Instruction
	Site Inspection Report Check	list		Answer and Exp as Necessar
a. Waste Analysis 140 CFR a. Waste Analysis Plan x x Adequate	265.13 as Incorporated in 400-	& b. Waste Analysis Resu		
	1.00		265	5.73(b)(3)
2. Security (264.14) [If a	pplicable]			
a. Access Control X X Adequate	More Effort Required	& b. Warning Signs Inadequate		Not Applicable
3. Inspection (265.15) a. Inspection Schedule x Adequate	More Effort Required	& b. Inspection Log (oper		rd) .73(b)(5)
4. Personnel Training (265	,16)			
a. Position Descriptions x Adequate	More Effort Required	& b. Training Records X Inadequate		t
	Ion Procedures (265.30 & 265.3			
a. Required Equipment (2		& b. Testing and Maintenar	nce of Equ	pment (265.33)
x x Adequate	More Effort Required	Inadequate		Not Applicable
c. Access to Communicati	ons or Alarm Systems (265.34)	& d. Required Aisle Space	(265.35)	
X X Adequate	More Effort Required	Inadequate		Not Applicable
e. Arrangements with Loc	More Effort Required	Inadequate	No	Applicable
			, — · ·	
6. Emergency Procedures (26 a. Contingency Plan (265	.52)	b. Instruction on Contin	gency Plan	
x x Adequate	More Effort Required f Implementation of Contingency	Inadequate		265.16(a)(2)
Adequate	More Effort Required	Inadequate	Not	Applicable
7. Waste Accountability				
	ed & Shipped (265.71 & 262.23)			
X Adequate	More Effort Required	Inadequate	Not	Applicable
	of HW within Facility (operat			
X Adequate	More Effort Required	Inadequate	Not	Applicable
. Closure				
a. Closure Plan (265.112)		b. Closure Cost Estimate	(265.142)	
X Adequate	x More Effort Required	Inadequate	Jpdate ne	eded 90 de
c. Financial Assurance fo	or Facility Closure (265.143 -	atter 1	August 1	1984
Adeauate	More Effort Required	Inadequate		
. Post-Closure (Disposal Fa	cility)		anna ishagani di seba menanga yangan sep	
a. Post-Closure Plan (265		b. Post-Closure Cost Est	mate (265	.144)
Adequate	More Effort Regulred	Inadequate		
A c. Financial Assurance fo	r Post-Closure Monitoring & Ma	Intenance (265.145 - by 4/	(13/82)	
etaupebA	More Effort Required	Inadequate		
. Liability Insurance (265.	147 - by 4/13/82)			

•											
ompany	Name _	CLIFTON	PRECIS	SION	Date of	Inspection	n	7/11/84		IAD D O	e 3 of 5 5 2 6 8 4 2 0
		STO	DRAGE FAC		SITE INSF 11 (Contal	PECTION REP	PORT C	HECKLIST			Instruction Answer and Explain as Necessary
ē.	-	tion of Cor Adequate				Required	r	Managemen†	of Conta dequate	iners (265	.173)
c.		ctions (26) dequate	5.174)	More	Effort Re	poliped		x Inadequ	uate		
d.	-	al Requirem Adequate				(265.176) & Required			lrements dequate	for Incom	patible Waste(265.177) Not Applicable
f.	Secur X X	Y†I etsupebA		M.	ore Effort	 Required	- 1	Required Em	nergency l		quipment Not Applicable
h.		Inment (26)	4.175)	More	Effort Re	equired		Inadequ	uate '		
1.	Estim	ated Type	and Numb	er of Co	ntainers						1
		39 - 55 (ating red									ventory on the
J.		ing/Markin dequate	g on Con	More	(262.31, :	32, 34) equired		Inadequ	uate		
		STORAGE AN	ID/OR TRE	ATMENT F	ACILITIES 12 (Ta		ECTION	REPORT C HI	ECKLIST		Instruction Answer and Explain as Necessary
8,		tion of Ta	anks (265	.192) More	e Effort R	equired		Inadeq			
b	Uncov	vered Tank Adequate		ents (26	55.192) More Effor	† Required			Continuou dequate	s Feed Red	Not Applicable
d.		ection (265 dequate	5.194)	More	effort R	equired		Inadeq	uate		
0.		al Require	ement for	IgnItab More	ole or Rea Effort R	ctive Wast equired	es (26	5.198) Inadeq	uate	П	Not Applicable
f.	Secur	1ty Adequate		М	lore Effor	t Required	-	Required E	qulpment dequate		Not Applicable

ITEM CODE

1.a. <u>Waste Analysis</u>, <u>Waste Analysis Plan</u>

Mr. Bohnsack indicated this facility has determined it is time to do a complete review of waste streams and analyze all existing waste streams. He indicated this would be done in the near future.

3.a. Inspection Schedule and Inspection Log

This facility has developed an inspection schedule and forms for inspection of emergency and safety equipment, including spill cleanup and fire fighting equipment. To this date, the forms documenting inspections have not been used. The forms and inspection schedule are part of the Part B application submitted approximately one year ago by this facility. The inspection of this equipment is required by 40 CFR 265.15. This facility must comply with these requirements by July 31, 1984.

4.b. Personnel Training, Training Records

The personnel training records indicated the last documented update of hazardous waste training, for those identified as needing hazardous waste training, was in December of 1982. An annual update of hazardous waste training is required by 40 CFR Sec. 265.16. This must be complied with by August 31, 1984. Submit documentation of this training to this office when in compliance.

7.a. Waste Accountability, Manifests

The manifests were reviewed and found to be complete and in compliance.

7.b. Waste Accountability, Description & Location of HW within Facility

The operating record kept by this facility was reviewed and found to be complete and in compliance. The list used as the operating record has the following information: the container number, location, accumulation start date, EPA waste number, description of contents, sample number and date, analysis number, manifest number, and shipment date.

The operating record also identified those containers from which samples would be collected. Tests will be performed on the samples collected, as part of the general reanalysis of the waste streams at this facility.

8.b. Closure, Closure Cost Estimate

The closure cost estimate is in need of an annual update. 40 CFR Sec. 265.142 requires the annual update of closure cost estimate. Submit the closure cost estimate to this office by August 31, 1984.

8.c. Closure, Financial Assurance for Facility Closure

The fiscal year for this facility begins on August 1, 1984. Within ninety (90) days of that date an updated financial assurance for facility closure must be developed as required by 40 CFR Sec. 265.143.

Clifton Precision

IAD005268420

ITEM CODE

11.c. Storage Facilities, Inspections

The storage area inspection forms were developed approximately one year ago as part of the original Part B application. To this date the storage area inspection forms have not been used as documentation of container storage area inspection. This facility must document a minimum of weekly inspection of hazardous waste container storage area. These inspections are required by 40 CFR Sec. 265.174. This must be complied with by July 31, 1984.

The inspection of the containers revealed that additional head space is needed in some solvent containers. It is recommended a minimum of 3" of head space be allowed in containers of hazardous waste solvent and waste oil.

SUMMARY OF RECOMMENDATIONS


- 1) Document weekly inspections of the hazardous waste storage area beginning no later than July 31, 1984.
- 2) Document inspection of safety and clean up equipment, as required by 40 CFR Sec. 265.15, beginning no later than July 31, 1984.
- 3) Submit an updated closure cost estimate to this office by August 31, 1984.
- 4) Submit documentation of an annual update of hazardous waste training to this office by August 31, 1984.

DNW: aw

inerals on other list

current as of March 9/84

20/1	EFA	CONTENT	THE EPA CONTENT
19	FOOT	WASTE ACH	1
28	FOOT	// //	D 110 [FOID]: HERY OIL-SLUDGE
2.9	F007	<i>p p</i>	
30	FOOT	<i>ji ji</i>	139 DOOS SANDO-FIX SZAL
32	FOOT	ji ji	139 DOOS SANDO-FIX SEAL
33	FOOT	11 11	170 DOOZ 181DITE 14-2
3 9	FOOT	1) //	151 5.1.5
35	F007	73 11	1100000 14-2
89	F00)	ll pi	1110112 172
88	FOOT	a n	173 DC02 181D17E 14-2
117	FOOT	TRICHLORDACETIC	-150 FOOT WIS CHICKWATED
118	FOOT		151 FOOT 11
169	FOOT	PHOSPHOAIC .	
149	FC05	WASTE SCHUSUTS	
152	F005		159 FON 11
153	F055	-4	161 FOM 11
150	FCOT	11	163 FOOT 11
15)	FOOT	//	154 FOOI 11
158	FOOS	_I I	166 FOOI - 11
160	FOOS	"	165 FOT 11
163	FOCS	of	134 - 1001 - 1
165	F005	**	176 5001 1
168 1	F005	ø	177 FOOT 11
175 F	005		reploditioner i hicates



25 of June 18,8

5 on rel #

178

79

80

81

87

189

